
## GLIDE-OUT 100

# WHEN DO YOU NEED A GLIDE-OUT?

- Floor space is too restricted to access racking with forklift
- Workers are leaning too far into existing shelving to hand pick heavy items
- Machine down time is excessive between die/tool changes
- Tooling, dies or material is too valuable to handle with forklift



 Stock parts are not visible due to deep shelving/racking



### PRODUCTION STORAGE SYSTEMS

### GLIDE-OUT 100

# AUTOMOTIVE AIRCRAFT ENERGY PLUMBING & HEATING PHARMACEUTICAL CHEMICAL PLASTICS TOOL & DIE STEEL FABRICATION PRINTING

Stamping dies, test motors, assembly components, tool crib components

Turbine components, engine components, dies

Valves, pumps, hydraulic pumps, production tooling, compressor parts, precision drill heads, breaker boxes

Generators, valves, pumps, fans

Pumps, valves


Paints, coatings, fluids, cylinder gas, adhesives

Injection molds, castings

Machine parts, heavy tooling

Specialty metals, pressbrake tooling, coil storage

Printing plates, printing cylinders















P.O. Box 205, Alpena, Michigan 49707